

April 13, 2022

Nicholas Carlson Assistant Public Manager Roxborough Village Metro Re: Roxborough - Airplane Park Safety Survey

Nicholas,

This report is in follow-up to the safety survey completed on March 15, 2022. The purpose of the survey was to identify potential safety hazards.

Attached, is a list of safety observations and recommendations based on conditions present at the time of my visit. If you have any questions or require additional information after reading this report, please don't hesitate to contact me.

Sincerely,

Adam Johnsen, CSP

Adam Johnsen, CSP Safety Management Consultant Colorado Special Districts Property and Liability Phone: (720) 375-2396 Email: ajohnsen@mcgriff.com

DISCLAIMER: Observations and recommendations are purely advisory and based on practices and conditions observed and information provided at the time of this survey. Observations and recommendations are not intended to include every loss or accident potential. It's the report recipient's responsibility to make further observations and take whatever action that may be necessary to prevent losses, enforce safety procedures and eliminate hazardous conditions so as to comply with any federal, state, or local law, rule or regulation concerning safety and health.

Report Summary

Report Name: Completed for: Inspection Date: Score: Roxborough - Airplane Park Roxborough Village Metro March 15, 2022 22.9%

Findings:

General Maintenance					
Issue Identified	There is not 9 inches of surface material				
Recommendation	Ensure that there is minimum of 9 inches of surface material. It is recommended that you add enough material to have 12 inches of material so that there is 9 inches after compaction and after material is pushed around. [ASTM F1292] <u>View ASTM Site</u>				
Issue Identified	There is/are not rust, rot, cracks, or splinters on at least some equipment				
Recommendation	Mitigate all rust, rot, cracks, or splinters on any equipment (check carefully where it comes in contact with the ground). [reference ASTMI 1487, CPSC] <u>View ASTM Site</u>				
	Notes: The steps are worn and getting worse. Rust is coming through and this is only going to get worse. This is the 2nd time that I have mentioned it.				
	Severity: Low (minor impact)				
	Contributing Factor: Equipment				
Photo(s)					

General Upkeep of Playgrounds

Positive Finding	There are no missing trash receptacles			
Positive Finding	There are no damaged fences, benches, or signs on the playground			
Positive Finding	Playground is free from evidence of vandalism			
Issue Identified	The signs used for play areas are not legible or are not in good repair			
Recommendation	Maintain the signs in the park so they are legible and in good repair. [reference ASTMI 1487, CPSC] <u>View ASTM Site</u>			

Notes: There is no playground signage due it becoming blacked out. Severity: Advisory (negligible impact) Contributing Factor: Administrative

Photo(s)



Issue IdentifiedThere is not proper signage at the playgroundRecommendationInstall proper signage at the playground. [ASTM F1487 -14] View ASTM Site

Equipment: Composite Structure

Positive Finding	There are no obstructions in the playground use zone
Issue Identified	There are broken or cracked pieces on the equipment
Recommendation	Repair and or replace broken or cracked pieces on the equipment. [reference ASTMI 1487. CPSC] View ASTM Site

Notes: Multiple corners are cracked on the slide. Replace the slide tunnel. This is the 2nd time that I have noted this on an inspection Severity: Moderate (marginal impact) Contributing Factor: Equipment

Photo(s)



Issue IdentifiedThere is an entanglement or head entrapment hazardRecommendationAddress the issues immediately. [ASTMI 1487] View ASTM Site

Notes: The top of the slide is a head entrapment hazard. The small probe can go through the gap between the slide and the barrier. The large one cannot. This is true for both sides of the slide.

This slide also appears to be a replacement and not designed for this equipment.

This is the 2nd time that I have mentioned this head entrapment hazard. Severity: Critical/Catastrophic (deducts 10%) Contributing Factor: Equipment

Photo(s)





Issue Identified Recommendation

edThere is an entanglement or head entrapment hazardationAddress the issues immediately. [ASTMI 1487] <u>View ASTM Site</u>

Notes: There is a clear plexiglass wind shield that is missing from the plan. With this piece missing there is a head entrapment hazard and it needs to be repaired ASAP. This is the 2nd time that I have brought this up in an audit. Severity: Critical/Catastrophic (deducts 10%) Contributing Factor: Equipment

Photo(s)



Equipment: Slide

Positive FindingThere are no protrusions on the structurePositive FindingThe slide exit heights are correct

Equipment: Climbing Elements				
Issue Identified	There are loose, missing bolts or nuts on the equipment			
Recommendation	Replace and or tighten the nuts in accordance with manufactures instructions. [reference ASTMI 1487, CPSC] <u>View ASTM Site</u>			

Notes: Missing screw Severity: Moderate (marginal impact) Contributing Factor: Equipment

Photo(s)



Score Summary	#	Severity Summary	Qty
Issues Identified:	8	N/A (Not Assigned)	2
Positive Findings:	6	Advisory (negligible impact)	1
Total Findings:	14	Low (minor impact)	1
Percent Positive:	42.9%	Moderate (marginal impact)	2
Severity Adjustment:	20.0%	Serious/Extreme (deducts 5%)	0
Final Score:	22.9%	Critical/Catastrophic (deducts 10%)	2

Submitted by: Adam Johnsen, CSP Safety Management Consultant Colorado Special Districts Property and Liability (720) 375-2396 ajohnsen@mcgriff.com

DISCLAIMER: Observations and recommendations are purely advisory and based on practices and conditions observed and information provided at the time of this survey. Observations and recommendations are not intended to include every loss or accident potential. It's the report recipient's responsibility to make further observations and take whatever action that may be necessary to prevent losses, enforce safety procedures and eliminate hazardous conditions so as to comply with any federal, state, or local law, rule or regulation concerning safety and health.